

Model R7150

Contact /
Non-Contact
Tachometer
with Laser



Instruction Manual

Table of Contents

2
2-3
4
4-5
6

Features

- Dual function unit with both contact and non-contact capabilities
- Provides fast and accurate RPM measurements of rotating objects and surface speed measurements MPM (meter per min) and FPM (feet per min)
- Laser provides improved accuracy at a greater distance
- Internal memory recalls min/max and last value
- Large LCD Display reverses depending on measurement mode
- Includes reflective tape, large and small cone tip adapters, funnel adapter, wheel adapter, batteries, and hard carrying case

Specifications

RPM Range (Contact): 0.5 to 19,999 RPM Range (Photo): 10 to 99,999

Surface Speed Range: 0.05 to 1,999.9 m/min 0.2 to 6.560 ft/min

0.2 to 6,560 π/min

Resolution: Photo: 0.1 RPM (≤999.9) / 1 RPM (≥1000)

Contact: 0.1 RPM (≤999.9) / 1 RPM (≥1000) Surface: 0.01 m/min (≤99.9) / 0.1 m/min (≥100) /

0.1 ft/min (<999.9) / 1 ft/min (>1000)

Basic Accuracy: $\pm (0.05\% + 1 \text{ dgt.})$

Visible Indicator: Yes (Laser)

Target Distance: 6.5ft (2000mm) (Photo)

Response Time: <1 sec

Sampling Time: Photo: 1 sec (over 60 RPM)

Contact: 1 sec (over 6 RPM)

Display Size/Type: 5 Digit LCD Display

Auto shut-off: Yes

Internal Memory: Max, Min and Last

Laser Class: Class II

Low Battery Indicator: Yes

Power Supply: 4 x AA Batteries

Product Certifications: CE

Operating Temperature: 32 to 122°F (0 to 50°C)
Storage Temperature: -4 to 140°F (-20 to 60°C)

Operating Humidity: 10-80% RH

Dimensions: 8.5 x 2.6 x 1.5" (215 x 65 x 38 mm)

Weight: 10.6oz (300g)

Optional accessories: Replacement Measuring Wheel (AS-35)

Replacement Cone Tip (CONE)

Reflective Tape (RT100) Soft Carrying Case (CA-05A) Soft Carrying Case (C-820)

Instrument Description

- 1. Laser Beam
- 2. RPM Adapter
- Display
- 4. Measure Button
- 5. Memory Call Button
- 6. Function Switch



Operating Procedures

Photo laser tachometer measuring procedure

- 1. Move the Function Switch to the Photo RPM position.
- Apply reflective tape to the object being measured. Press the Measure Button and align the Laser Beam with the applied target. Verify that the Monitor Indicator provides a reading when the target passes through the field of view. Release the Measure Button when the reading stabilizes.

Note: If the measured RPM value is very low (ie: 50 RPM), we recommend attaching more **Reflective tape**.

Contact tachometer measuring procedure

RPM measurement


- Move the Function Switch to the Contact RPM position.
- Press the Measure Button and lightly pressing the RPM Adapter against the rotating axis. Release the Measure Button when the reading stabilizes.

Surface Speed Measurement

- 1. Move the **Function Switch** to the **m/min.** or **ft/min**. position.
- Press the Measure Button and attach the surface speed test wheel to the detector. Release the Measure Button when the reading stabilizes.

Operation procedure for memory recall

- Last value, Max. value and min. value are automatically stored in memory.
- 2. To recall measurements saved in memory:
 - a. Push the Memory Call Button To display the last value (LA and the last value will be displayed alternately).
 - b. Push the Memory Call Button again To display the maximum value (UP and the max. value will be displayed alternately).
 - Push the Memory Call Button again To display the minimum value (dn and the min. value will be displayed alternately).



Battery Replacement

- When the LCD displays LO, it is necessary to replace the batteries, however in-spec measurements may still be made for several hours after the low battery indicator appears.
- Open the Battery Cover, using a flat screwdriver or small coin.
- Replace batteries correctly and place the cover back on.

For service on this or any other REED product or information on other REED products, contact REED Instruments at info@reedinstruments.com

Notes			