

## **Data Acquisition Software** Model R3002

SOFTWARE GUIDE

## R3002 Digital Manometer Software Features

Compatible with Microsoft Windows© XP, Vista / 7 / 8 / 10 Connectivity: USB

## Software Features

- Device data management: Erase/load instrument data, Remotely control instrument (Figure 1)
- Set your sample rate (Figure 2)
- Track data in real-time and calculate statistics on the fly (Figure 3)
- Export data to Microsoft Excel (See sample data, Figure 4)





Figure 1

Figure 2





Dialog			ļ
Sample Rate 1	5	Sec	
	OK		

Figure 4

DATA

UNIT

-0.006 psi

-0.006 psi

-0.036 psi

-0.05 psi

-0.07 psi

-0.073 psi

-0.006 psi

-0.005 psi

-0.005 psi -0.045 psi

-0.026 psi

-0.089 psi

-0.028 psi

-0.005 psi

-0.005 psi

-0.006 psi

-0.005 psi

-0.006 psi

-0.006 psi

0.026 psi

0.032 psi

16

17

18

19

20

21

22

23

23

0 psi

TIME

16:37:30

16:37:31

16:37:32

16:37:33

16:37:34

16:37:35

16:37:36

16:37:37

16:37:38

16:37:39

16:37:40

16:37:41

16:37:42

16:37:43

16:37:44

16:37:45

16:37:46

16:37:47

16:37:48

16:37:49

16:37:50

16:37:51

16:37:52

16:37:53